

# Airframe ADs: Model V35B/V35B-TC Bonanza

from www.faa.gov

AD Number	Title	Subject	Effective
2009-25-01	<a href="#">Hawker Beechcraft Corporation Models 58, 58A, 58P, 58PA, 58TC, 58TCA, 95-B55, 95-B55A, A36, A36TC, B36TC, E55, E55A, F33A, and V35B Airplanes</a>	Shoulder harnessess	01/08/2010
2008-13-17	<a href="#">Hawker Beechcraft Corporation (Type Certificates No. 3A15, No. 3A16, No. A23CE, and No. A30CE Previously Held by Raytheon Aircraft Company) F33 Series and Models G33, V35B, A36, A36TC, B36TC, 95-B55, D55, E55, A56TC, 58, 58P, 58TC, G58, and 77 Airplanes</a>	Circuit breaker toggle switches	08/06/2008
2007-08-08	<a href="#">Raytheon Aircraft Company (The Beech Aircraft Company and BEECH previously held Type Certificate Nos. 3A15, 3A16, 5A3, and A-777) Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A45 (T-34A, B45), D45 (T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T-42A), 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes</a>	Uplock roller	05/25/2007
2001-08-08	<a href="#">Raytheon Aircraft Company Beech Models 35-C33A, E33A, E33C, F33A, F33C, S35, V35, V35A, V35B, 36, and A36 Airplanes</a>	V-band Exhaust Clamp	06/07/2001
99-05-13	<a href="#">Raytheon Aircraft Company 17, 18, 19, 23, 24, 33, 35, 36/A36,</a>	Fuel Tank Selector	04/19/1999

# Airframe ADs: Model V35B/V35B-TC Bonanza

from [www.faa.gov](http://www.faa.gov)

	<a href="#">A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes</a>		
99-05-13 R1 WD	<a href="#">Raytheon Aircraft Company Beech 17, 18, 19, 23, 24, 33, 35, 36/A36, A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes</a>	Withdrawal of AD 99-05-13	07/05/2000
97-14-15	<a href="#">Raytheon Aircraft Company (formerly known as Beech Aircraft Corporation) Models E33, F33, G33, E33A, F33A, E33C, F33C, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, V35TC, V35ATC, V35BTC, 36, A36, A36TC, B36TC, 50, B50, C50, 95-55, 95A55, 95B55, 95C55, D55, E55, 56TC, A56TC, 58, 58TC, 95, B95, B95A, D95A, and E95 Airplanes.</a>	Cabin Side Door And Utility Door Handle	09/02/1997
97-06-11	<a href="#">Raytheon Aircraft Company (formerly Beech Aircraft Corporation) 35 Series Airplanes</a>	Ruddervator Differential Tail Control Rod Assy	05/16/1997
95-04-03	<a href="#">Beech Aircraft Corporation 33, 35, and 36 Series Airplanes</a>	Wing Spar	04/07/1995
94-20-04	<a href="#">Beech Aircraft Corporation 35 Series Airplanes</a>	V-Tail Structure	11/28/1994
94-20-04 R1	<a href="#">Raytheon Aircraft Company Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A and V35B Airplanes</a>	V-tail	12/10/2002
94-20-04 R2	<a href="#">Raytheon Aircraft Company Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, and V35B Airplanes</a>	Empennage aft fuselage	06/27/2003
92-17-01	<a href="#">Beech Models A36TC, S35, V35, V35A and V35B Airplanes</a>	Fuel Metering Unit	09/11/1992

## Airframe ADs: Model V35B/V35B-TC Bonanza

from [www.faa.gov](http://www.faa.gov)

91-20-08	<a href="#">Airworthiness Directives: Beech Models F33A, F33C, V35B, A36, A36TC and B36TC Airplanes</a>	Fresh Air Blower Housing	10/31/1991
91-18-19	<a href="#">Beech Models F33A, V35B, A36, B36TC, 95-B55, 95-B55A, E55, E55A, 58, 58A, 58P, 58PA, 58TC, and 58TCA Airplanes</a>	Pilot Shoulder Harnesses	10/21/1991
88-21-02	<a href="#">Beech Model F33A, F33C, V35B, A36, A36TC, B36TC, 95-B55, 95-B55A, E-55, E-55A, 58, 58A, 58P, 58PA, 58TC and 58TCA Airplanes</a>	Seat Tracks	10/31/1988
87-18-06 R1	<a href="#">Beech Model F33A, V35B, A36, A36TC, B36TC, E55, 58, 58A, 58P, 58PA, 58TC and 58TCA Airplanes</a>	Seat Recline Actuator Handle	02/05/1988
84-09-01	<a href="#">Beech Models E33, F33, G33, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35TC, V35A, V35A-TC, V35B, V35B-TC, 36, A36, A36TC, 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 95-B55B, 56TC, A56TC, 58, 58A, 58TC, 58TCA, 95, B95, B95A, D95A and E95</a>	Window Emergency Egress Provision	05/25/1984
79-01-01	<a href="#">Beech Models F33A, F33C, G33, 35-C33, 35-C33A, 35-B33, V35B, A36, D55, D55A, E55, E55A, 56TC, 58, 58A, 58P, 58PA, 58TC, 58TCA, 65-B80, 70, B90, C90, E90, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, 99, 99A, A99A, B99, 100, A100, B100, 200, 200T Airplanes</a>	Screws in Control System	01/08/1979
76-22-02	<a href="#">Beech Models F33A, F33C, V35B, A36, 95-B55, 95-B55A, E55,</a>	Y Type Shoulder Harness	06/02/1977

# Airframe ADs: Model V35B/V35B-TC Bonanza

from www.faa.gov

	<a href="#">E55A,58, 58A, 65-B80, C90, E90, B99, A100, B100, and 200 Airplanes</a>		
75-05-02	<a href="#">BEECH, CESSNA, NAVION AND PIPER Models 35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36 Series and Piper Models PA24, PA24-250, PA24-260 Series, Navion Model Navion A Series, Cessna Models 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P Series Airplanes</a>	Engine Oil	02/21/1975
75-01-07	<a href="#">BEECH Models S35, V35, V35A and V35B Airplanes</a>	Exhaust System Failures	01/13/1975
74-24-03	<a href="#">BEECH Models F33A, V35B, A-36, 95-B55 and 95-B55A, E55 and E55A. 58 and 58A, A60 and B60, 70, B80, C90, E90, B99, 100 and A100, 200, airplanes.</a>	Strobe Light System	11/22/1974
74-03-02	<a href="#">Airworthiness Directives: BEECH Models F33A , V35B, A36, 95-B55, 95-B55A, E55, E55A, 58 and 58A Airplanes.</a>	Landing Gear Shock Strut Piston	02/05/1974
73-14-03	<a href="#">BEECH Model F33A, F33C, V35B, A36, 95-B55, 95-B55A, E55, E55A, 58, 58A Airplanes</a>	Landing Gear Shock Strut Piston	07/06/1973
72-22-01	<a href="#">BEECH Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35TC, V35A, V35A-TC, V35B and V35B-TC, 36, A36,</a>	Landing Gear Uplock Rollers	10/25/1972

# Airframe ADs: Model V35B/V35B-TC Bonanza

from [www.faa.gov](http://www.faa.gov)

	<a href="#"><u>A45(T-34A), B45, D45(T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes</u></a>		
72-11-02	<a href="#"><u>BEECH Models F33, G33, F33A, V35B, V35B-TC, A36, 95-B55, 95-B55A, 95-B55B, E55, E55A, 58, 58A, 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, E33C, F33C, K35, M35, N35, P35, S35, V35, V35-TC, V35A, V35A-TC, 36, 35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, D55, D55A, 95, B95, B95A, D95A and E95 Airplanes</u></a>	Engine Fuel Interruption	05/20/1972
71-24-10	<a href="#"><u>BEECH Models 35-C33, E33, F33, 35-C33A, E33A, F33A, E33C, F33C, V35, V35TC, V35, V35A-TC, V35B, V35B-TC, 36, A36, 95-B55, 95-B55A, 95-C55, D55, E55, 56TC, A56TC, 58, D95A, E95</u></a>	Security of Control Wheel	08/01/1973