



November 16, 1987
G-87-99

TO ALL BEECHCRAFT AVIATION AND AERO CENTERS, PARTS WHOLESALERS, AND ALL
INTERNATIONAL DISTRIBUTORS AND DEALERS.

ATTENTION: Service Managers and Parts Managers

SUBJECT: Communique Index For Beech Piston Powered Aircraft.


Attached is an Index for all Beechcraft Executive Service and Safety
Communiques which have been issued on the Beech Models 19, 23, 24, 76, 77 and
the Bonanza, Baron, Duke, Queen Air Models, plus the Model 18's.

This index should be filed with your Communiques for quick reference.

Thank you.

Very truly yours,

BEECH AIRCRAFT CORPORATION



Ron Gros
Assistant Manager
Commercial Service

RJG:dh



EXECUTIVE AIRCRAFT SERVICE COMMUNIQUE INDEX

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
00	<u>Aircraft General</u>	- - - -
	Announcement of Communique	1
	Queen Air Inspection Publications	(S) No. 07
	Bonanza Excessive Speed Accidents	(S) No. 55
	Information For Pilots & Owners	(S) No. 24
	Implementation of Safe One Engine Inoperative Speed	(S) No. 46A
	Wake Turbulence	(S) No. 65
	Reduce Speed on Bonanza V-Tail A/C	(S) No. 74
	Icing	(S) No. 32A
	Placard Kits For V-Tail Bonanza's With Reduced Speed	No. 81
	Effects of Facial Hair With Oxygen Masks	(S) No. 79
06	<u>Dimensions & Areas</u>	- - - -
07	<u>Lifting & Shoring</u>	- - - -
	58P & TC Jacking Procedures	57
	58P & TC Jacking Procedures	75
08	<u>Leveling & Weighing</u>	- - - -
	P.O.H. Change - Weight & Balance	7
	Duke P.O.H. Change - Wet Wing Tips	22

(S) - Denotes a Safety Communique.

<u>ATA CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE NO.</u>
09	<u>Towing & Taxing</u>	- - - -
	Model 60 Tow Pins	35
10	<u>Parking & Mooring</u>	- - - -
11	<u>Placards & Markings</u>	- - - -
	Decal Installations	35
12	<u>Servicing</u>	- - - -
	Duke Windshield Rain Repellent	6
	Ni-Cad Battery Information	8
	Fuel Allocation	14
	Fuel Availability 80/87	20
	Duke Air Conditioner Oil Quantity	10
	Champion Oil Filters	29
	T.C.M. Corrosion Preventative Oil	51
	T.C.M. Oil Filter Adaptors	(S) No. 44
	Elevator Trim Tab Freezing	(S) No. 57
	Magnesium Treatment	82
20	<u>Airframe</u>	- - - -
	Standard Practices - Airframe	- - - -
	Corrosion Treatment of Magnesium	44
	Plastic Bead Paint Removal	80

(S) - Denotes a Safety Communique.

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
21	<u>Air Conditioning</u>	- - - -
	Duke Air Conditioner Oil Quantity	10
	Model 58P Ventilation	23
	58P Nacelle Scoop Actuators	27
	Cabin Heater Fuel Systems	27
	Bonanza Condenser Door Actuator	35
	Janitrol Heater Drain Fittings	61
	Duke Air Conditioner Clutch	(S) No. 64
	Receiver-Dryer Kits For Barons	65
	Heater Clamp Sealant On Pressurized A/C	65
	New Air Conditioner Drive Belt & Pulley	68
	Baron Air Conditioner Freon Capacity Change	68
21A	<u>Pressurization</u>	- - - -
	Duke Pressurization Adj. Procedures	2
	Model 60 Pressurization	18
	58P Aft Cabin Door	19
	58P Door Seal Light Improvement	40
	58P Door Seal Pump Installation	54
	Cabin Door - All Pressurized Aircraft	(S) No. 39
22	<u>Auto Flight</u>	- - - -

(S) - Denotes a Safety Communique.

23	<u>Communications</u>	- - - -
	ELT Remote Switch	56
	Narco ELT 10 Emerg. Locator Transmitter	82
24	<u>Electrical Power</u>	- - - -
	Duke Voltage Regulator Adj.	6
	Ni-Cad Battery Information	8
	Duke Air Cooled Batteries	10
	Ni-Cad Battery Monitoring Systems	11
	Ni-Cad Battery Monitoring Systems	12
	Ni-Cad Battery Monitoring Systems	13
	58P External Power	23
	Alternator Drive Pulley Torque	25
	Change From 12V to 24V Electrical Systems	36
	Improved 12V Starter Relay (See No. 70 For Amendment)	62
	24V. Regulators in Bonanzas	62
25	<u>Equipment/Furnishings</u>	- - - -
	Aft Seat Stops	18
	Arm Rest Coating	27
	58P Nose Baggage Light	27
	Shoulder Harness Bracket Cover	31
	24 Volt Cigarette Lighter	34
	Model 18 Aft Partition Door	(S) No. 13
	Internally Lighted Altimeters	(S) No. 21

(S) - Denotes a Safety Communique.

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
25	<u>Equipment/Furnishings - (Continued)</u>	- - - -
	Bonanza/Baron Seat Back Stop	66
	Rotating Beacons (Whelan)	77
	Insp. Seat Belt Buckles	(S) No. 73
	Cargo Tie-Down Web Buckles	84
27	<u>Flight Controls</u>	- - - -
	Aileron Tab Linkage Replacement	31
	Control Column Lock Pin Removal	44
	New P/N Flap Motor Brushes	44
	Elevator Trim Tab Freezing	(S) No. 57
	Queen Air Elevator Torque Valve	54
	Adjustable Link Kit For Model 36 & A36TC	65
	Bonanza Ruddervator Rigging	69
	Quick-Clamp Cockpit Work Station	(S) No. 72
28	<u>Fuel</u>	- - - -
	Bendix Fuel Flow Information	2
	Minimum Fuel Flight Planning	2
	Heated Fuel Vents	3
	Fuel Allocations	14
	80/87 Fuel Availability	20
	Duke Mixture Cable Fire Sleeve	31
	B55 Fuel Pump Fittings	35
	Fuel Cell Installation	35

(S) - Denotes a Safety Communique

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
28	<u>Fuel</u> - (Continued)	- - - -
	Fuel Line Interference	40
	A36TC Aux. Fuel Pump Operation	45
	A36TC Fuel & M.P. Adjustment	49
	Fuel Vapor Return Check Valve	54
	Fuel Cell Nipple Torque	54
	T.C.M. Fuel Control Linkage	40
	Bonanza Fuel Selector	(S) No. 2
	Baron Fuel System Mod.	(S) No. 5
	Fuel Selector Valve Binding	(S) No. 25
	Bonanza Fuel Selector Valve	(S) No. 28
	Aerosonics Fuel Flow System	62
	60, 58, 58P, 58TC Fuel Selector Binding At Altitude	73
	Bonanza & Baron Reservoir Fuel Tank Sponge	(S) No. 67
	36TC Fuel Return Line Chaffing	78
	Automotive Type Fuel	(S) No. 80
	Water Contamination	(S) No. 81
	Fuel System In Single Engine A/C	85
30	<u>Ice & Rain Protection</u>	- - - -
	Heated Fuel Vents	3
	Oil Cooler Winter Baffles	3
	Duke Windshield Rain Repellent	6
	58P Pneumatic Pressure System	28

(S) - Denotes a Safety Communique.

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
30	<u>Ice & Rain Protection - (Continued)</u>	- - - -
	Duke Entrance Door Drip Shield	39
	Dry Air pump System Maintenance	44
	Drain Holes In Duke Fuselage	54
	Approval For Flight In Icing	(S) No. 32
	Icing Certification Of Barons	(S) No. 54
	Improved Baron Heated Windshield Temp. Control Box	73
32	<u>Landing Gear</u>	- - - -
	Duke Landing Gear Downlock Instl.	3
	Duke Landing Gear Downlock Kit	6
	58P & 60 Main Tires	23
	Duke Landing Gear Maintenance	18
	Interchangeable Landing Gear Motor	31
	Baron Nose Gear Taxi Lights	35
	58P, 58TC & 60 Brake Spring Removal	39
	Landing Gear Maintenance	44
	Loss of Effective Braking	54
	P/N Change of Electro-Mech Motors	54
	Goodyear Flight Custom II Tires	54
	Spar Cover Interference	57
	Wheel Lip Seals	57
	Landing Gear Actuator Change	57

(S) - Denotes a Safety Communique.

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
32	<u>Landing Gear</u> - (Continued)	- - - -
	Fuel Line Interference	40
	Landing Gear Actuator Change (Revision to Comm. #57)	61
	Landing Gear Wheel Lip Seals	61
	Goodyear Flight Custom II Tires	62
	Landing Gear Motor Change (Revision to Comm. #57)	64
	Landing Rigging With Battery	67
	Bonanza Nose Landing Gear Door Rigging	70
	Model 76 Duchess Landing "A" Frame	79
33	<u>Lights</u>	- - - -
	58P Nose Baggage Light	27
	Baron Nose Gear Taxi Lights	35
	Internally Lighted Altimeters	(S) No. 21
	58P Door Seal Annunciator Light	40
34	<u>Navigation</u>	- - - -
	Internally Lighted Altimeters	(S) No. 21
35	<u>Oxygen</u>	- - - -

(S) - Denotes a Safety Communique

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
36	<u>Pneumatic</u>	- - - -
	Bonanza Instrument Air Pressure	3
	58P Pneumatic Pressure System	28
	58P Pneumatic Air Filters	34
	Service History of Pneumatic Systems	42
	Dry Air Pump System Maintenance	44
	Airborne Service Letter No. 31	(S) No. 76
	Overhauled Dry Air Pumps	82
39	<u>Electrical Panel & Components</u>	- - - -
	Duke Voltage Regulator Adj.	6
	12 Volt to 24 Volt Electrical Systems	36
	58P Door Seal Annunciator Light	40
	Internally Lighted Altimeters	(S) No. 21
	Fuel Quantity Indication Systems	(S) No. 27
	Rotating Beacons (Whelen)	77
	<u>STRUCTURE</u>	
51	<u>Structures</u>	- - - -
	Model 18 Truss Inspection	21
	Model 60 Wing Bolt Installation	46
	Wing Attach Bolt Torque (Wet)	53
	Model 18 Truss Inspection	(S) No. 11
	Model 18 Wing Structure	(S) No. 36

(S) - Denotes a Safety Communique

<u>ATA CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE NO.</u>
52	<u>Doors</u>	- - - -
	58P Aft Cabin Door	19
	58P Nose Baggage Door Light	27
	Duke Door Drip Shield	39
	Model 18 Aft Partition Door	(S) No. 13)
	Cabin Door - Pressurized Aircraft	(S) No. 39
	Bonanza/Baron Cabin Door Rigging	69
	Bonanza/Baron Cabin Door Opening	(S) No. 68A
	Liberal A/C Cabin Door Opening	(S) No. 77
53	<u>Fuselage</u>	- - - -
	Duke Door Drip Shield	39
	Drain Holes in Duke Fuselage	54
	Model 77 Skipper Tail Skid	79
	All Aero Center, Delamination of Honeycomb Panels	79
54	<u>Nacelles/Pylons</u>	- - - -
	58P External Power	23
	Duke Voltage Regulator Adj.	6
	Split Nose Bug For Bonanzas	66
55	<u>Stabilizers</u>	- - - -
	Corrosion Treatment of Magnesium	44
	Queen Air Elevator Torque Valve	54
	Elevator Trim Tab Freezing	(S) No. 57

(S) - Denotes A Safety Communique.

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
56	<u>Windows</u>	- - - -
57	<u>Wings</u>	- - - -
	Model 60 Wing Bolt Installation	46
	Wing Attach Bolt Torque (Wet)	53
	Model 18 Wing Structure	(S) No. 36
	Model 19 Truss Inspection	21
<u>PROPELLER</u>		
61	<u>Propellers</u>	- - - -
	Hartzell Propeller Hub Change	27
	Hartzell & McCauley Propeller A.D.'s	32
	Hartzell Propeller Insp. - Travel Air	(S) No. 14 Revised 2-6-73
	Operating Air Charged Propellers	(S) No. 42
	S.B. on McCauley Prop Governors	(S) No. 76
<u>POWERPLANT</u>		
71	<u>Powerplant</u>	- - - -
	Model 65 Series Powerplant Maintenance	(S) No. 03
	Model 50 & 65 Powerplant Maintenance	(S) No. 48
	A36TC Hot Weather Operation	48
	Split Nose Buy For Bonanzas	66

(S) - Denotes a Safety Communique.

ATA
CHAPTER

SUBJECT

COMMUNIQUE
NO.

72

Engine

- - - -

Lycoming Cylinder Replacement	2
Lycoming Oil Cooler Winter Baffles	3
T.C.M. Alternator Pulley Torque	25
Duke Lycoming Engines	10
58P & TC Turbine Oil Supply	34
T.C.M. Induction Hose Clamps	35
B55 Fuel Pump Fittings	35
T.C.M. Starter Adapter Gaskets	37
T.C.M. Fuel Control Linkage	40
Model 35 Turbine Oil Inlet Port	(S) No. 10
Model 35 Turbocharger System Insp.	(S) No. 33
Anti-Scuff Additive For Lycoming Engine	62
A36TC and B36TC Engine Leakage Test (Cylinder Compression)	74
Insp. Cylinders for Cracking	(S) No. 69

73

Engine Fuel & Control

- - - -

Bendix Fuel Flow System Information	2
Model 76 Duchess Lord Mount Location	79
Duke Mixture Cable Fire Sleeve	31
B55 Fuel Pump Fittings	35
T.C.M. Fuel Control Linkage	40
A36TC Fuel Pump Operation	45
A36TC Fuel & M.P. Adjustment	49

(S) - Denotes a Safety Communique

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
73	<u>Engine Fuel & Control (Cont.)</u>	
	Fuel Vapor Return Check Valves	54
	Thompson Engine Driven Fuel Pump	55
	Large Washers on Engine Control Rod Ends	68 & 69
	36TC Fuel Line (Return) Chaffing	78
74	<u>Ignition</u>	- - - -
75	<u>Air</u>	- - - -
	T.C.M. Induction Hose Clamps	35
	A36TC & B36TC Engine Cooling	66
77	<u>Engine Indicating</u>	- - - -
	Bendix Fuel Flow System Information	2
	Calibration of Cylinder Head and T.I.T. Systems	75
78	<u>Exhaust</u>	- - - -
	56TC & 60 Extended Exhaust Stacks	18
	58P & 58TC Turbocharger Exhaust Pipe	(S) No. 58
	A36TC & B36TC Turbocharger Tail Pipe Instl.	70
	Alcor T.I.T. Test	82

(S) - Denotes a Safety Communique

<u>ATA</u> <u>CHAPTER</u>	<u>SUBJECT</u>	<u>COMMUNIQUE</u> <u>NO.</u>
79	<u>Oil</u>	- - - -
	Duke Oil Cooler Winter Baffles	3
	Champion Oil Filters	29
	58P & 58TC Turbine Oil Supply	34
	T.C.M. Corrosion Preventive Oil	51 Rev. II
	Model 35 Turbine Oil Inlet Port	(S) No. 10
	T.C.M. Oil Filter Adapters	(S) No. 44
	Wastegate Oil Line Chaffing on 58P & TC	65
80	<u>Starting</u>	- - - -
	T.C.M. Starter Adapter Gaskets	37
	58P & TC Starter Cable Clamping	40
	Bonanza Starter Energizer Light	70
81	<u>Turbines</u>	- - - -
	58P & TC Turbine Oil Supply	34
	A36TC Fuel & M.P. Adjustment	49
	Model 35 Turbine Oil Inlet Port	(S) No. 10
	Model 35 Turbocharger System Inspection	(S) No. 33
	Wastegate Oil Line Chaffing on 58P & TC	65

(S) - Denotes a Safety Communique