

Airframe ADs: Model B35 Bonanza

from www.faa.gov

AD Number	Title	Subject	Effective
2007-08-08	Raytheon Aircraft Company (The Beech Aircraft Company and BEECH previously held Type Certificate Nos. 3A15, 3A16, 5A3, and A-777) Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A45 (T-34A, B45), D45 (T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T- 42A), 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes	Uplock roller	05/25/2007
2002-21-13	Raytheon Aircraft Company Beech Models 35, 35R, A35, and B35 Airplanes	V-tail	12/10/2002
99-05-13	Raytheon Aircraft Company 17, 18, 19, 23, 24, 33, 35, 36/A36, A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes	Fuel Tank Selector	04/19/1999
99-05-13 R1 WD	Raytheon Aircraft Company Beech 17, 18, 19, 23, 24, 33, 35, 36/A36, A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes	Withdrawal of AD 99-05-13	07/05/2000
98-13-02	Raytheon Aircraft Company Models 35, A35, B35, and 35R Airplanes	Placard - Speed	07/07/1998
97-06-11	Raytheon Aircraft Company (formerly Beech Aircraft Corporation) 35 Series Airplanes	Ruddervator Differential Tail Control Rod Assy	05/16/1997
94-20-04	Beech Aircraft Corporation 35 Series	V-Tail Structure	11/28/1994

Airframe ADs: Model B35 Bonanza

from www.faa.gov

	Airplanes		
89-05-02	Beech Model 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, E33C, 35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35-TC, V35A, V35A-TC, 36, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, 56TC, 95, B95, B95A, D95A and E95 Airplanes	Elevator Control Fittings	03/24/1989
84-09-01	Beech Models E33, F33, G33, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35TC, V35A, V35A-TC, V35B, V35B-TC, 36, A36, A36TC, 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 95-B55B, 56TC, A56TC, 58, 58A, 58TC, 58TCA, 95, B95, B95A, D95A and E95	Window Emergency Egress Provision	05/25/1984
76-05-04	BEECH Models 35, 35R, A35 and B35 and Pine Air Model Super- V Airplanes	Stabilizer Attach Fitting	
75-15-08	BEECH AND CESSNA Models 35, A35, B35, C35, D35, E35, F35, 35R, 35-33, 35-A33, 35- B33, 35-C33, H35, J35, K35, M35, N35, P35; Cessna Models 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, A150K, 150L and A150L Series Airplanes	Engine Lubrication	09/10/1975
75-05-02	BEECH, CESSNA, NAVION AND PIPER Models 35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33,	Engine Oil	02/21/1975

Airframe ADs: Model B35 Bonanza

from www.faa.gov

	<u>35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36 Series and Piper Models PA24, PA24-250, PA24-260 Series, Navion Model Navion A Series, Cessna Models 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P Series Airplanes</u>		
72-22-01	<u>BEECH Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35TC, V35A, V35A-TC, V35B and V35B-TC, 36, A36, A45(T-34A), B45, D45(T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes</u>	Landing Gear Uplock Rollers	10/25/1972
72-18-01	<u>BEECH Models 35, A35, B35 and C35 Airplanes</u>	Fuel Selector Valve Warning Light	08/29/1972
72-11-02	<u>BEECH Models F33, G33, F33A, V35B, V35B-TC, A36, 95-B55, 95-B55A, 95-B55B, E55, E55A, 58, 58A, 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, E33C, F33C, K35, M35, N35, P35, S35, V35, V35-TC, V35A, V35A-TC, 36, 35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, D55, D55A, 95, B95, B95A, D95A and E95 Airplanes</u>	Engine Fuel Interruption	05/20/1972

Airframe ADs: Model B35 Bonanza

from www.faa.gov

69-18-01	BEECH Model 35, A35, B35 and C35 Airplanes	Fuel System Modification	08/30/1969
63-25-01	Revision: BEECH Model 35, Model 35R, A35, or B35 Aircraft	Fuselage Modification	
62-08-03	Beech Models 35-33, 35-A33 and 35-B33, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50, 95-55 and 95-A55, 65, 95, B95 and B95A Airplanes	Control Wheels	07/09/1970
59-08-01	Beech Models A35, B35, C35 Aircraft	Landing Gear Limit Switches	
53-01-02	Beech Models 35, A35, B35 and C35 Airplanes	Fuel Selector Valve Rework	