

Airframe ADs: Model S35 Bonanza

from www.faa.gov

AD Number	Title	Subject	Effective
2007-08-08	Raytheon Aircraft Company (The Beech Aircraft Company and BEECH previously held Type Certificate Nos. 3A15, 3A16, 5A3, and A-777) Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36, A45 (T-34A, B45), D45 (T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B (T- 42A), 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes	Uplock roller	05/25/2007
2001-08-08	Raytheon Aircraft Company Beech Models 35-C33A, E33A, E33C, F33A, F33C, S35, V35, V35A, V35B, 36, and A36 Airplanes	V-band Exhaust Clamp	06/07/2001
99-05-13	Raytheon Aircraft Company 17, 18, 19, 23, 24, 33, 35, 36/A36, A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes	Fuel Tank Selector	04/19/1999
99-05-13 R1 WD	Raytheon Aircraft Company Beech 17, 18, 19, 23, 24, 33, 35, 36/A36, A36TC/B36TC, 45, 50, 55, 56, 58, 58P, 58TC, 60, 65, 70, 76, 77, 80, 88, and 95 Series Airplanes	Withdrawal of AD 99-05-13	07/05/2000
97-14-15	Raytheon Aircraft Company (formerly known as Beech Aircraft Corporation) Models E33, F33, G33, E33A, F33A, E33C, F33C, C35, D35, E35, F35, G35, H35, J35, K35,	Cabin Side Door And Utility Door Handle	09/02/1997

Airframe ADs: Model S35 Bonanza

from www.faa.gov

	<u>M35, N35, P35, S35, V35, V35A, V35B, V35TC, V35ATC, V35BTC, 36, A36, A36TC, B36TC, 50, B50, C50, 95-55, 95A55, 95B55, 95C55, D55, E55, 56TC, A56TC, 58, 58TC, 95, B95, B95A, D95A, and E95 Airplanes.</u>		
97-06-11	<u>Raytheon Aircraft Company (formerly Beech Aircraft Corporation) 35 Series Airplanes</u>	Ruddervator Differential Tail Control Rod Assy	05/16/1997
95-04-03	<u>Beech Aircraft Corporation 33, 35, and 36 Series Airplanes</u>	Wing Spar	04/07/1995
94-20-04	<u>Beech Aircraft Corporation 35 Series Airplanes</u>	V-Tail Structure	11/28/1994
94-20-04 R1	<u>Raytheon Aircraft Company Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A and V35B Airplanes</u>	V-tail	12/10/2002
94-20-04 R2	<u>Raytheon Aircraft Company Beech Models C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35A, and V35B Airplanes</u>	Empennage aft fuselage	06/27/2003
92-17-01	<u>Beech Models A36TC, S35, V35, V35A and V35B Airplanes</u>	Fuel Metering Unit	09/11/1992
89-05-02	<u>Beech Model 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, E33C, 35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35-TC, V35A, V35A-TC, 36, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, 56TC, 95, B95, B95A, D95A and E95 Airplanes</u>	Elevator Control Fittings	03/24/1989
84-09-01	<u>Beech Models E33, F33, G33, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35,</u>	Window Emergency Egress Provision	05/25/1984

Airframe ADs: Model S35 Bonanza

from www.faa.gov

	V35TC, V35A, V35A-TC, V35B, V35B-TC, 36, A36, A36TC, 50, B50, C50, D50, D50A, D50B, D50C, D50E, E50, F50, G50, H50, J50, 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 95-B55B, 56TC, A56TC, 58, 58A, 58TC, 58TCA, 95, B95, B95A, D95A and E95		
75-05-02	BEECH, CESSNA, NAVION AND PIPER Models 35, A35, B35, C35, D35, E35, F35, G35, 35R, 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 36, A36 Series and Piper Models PA24, PA24-250, PA24-260 Series, Navion Model Navion A Series, Cessna Models 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P Series Airplanes	Engine Oil	02/21/1975
75-01-07	BEECH Models S35, V35, V35A and V35B Airplanes	Exhaust System Failures	01/13/1975
72-22-01	BEECH Models 35-33, 35-A33, 35-B33, 35-C33, E33, F33, G33, 35-C33A, E33A, F33A, E33C, F33C, 35, A35, B35, C35, D35, E35, F35, G35, H35, J35, K35, M35, N35, P35, S35, V35, V35TC, V35A, V35A-TC, V35B and V35B-TC, 36, A36, A45(T-34A), B45, D45(T-34B), 95-55, 95-A55, 95-B55, 95-B55A, 95-C55, 95-C55A, D55, D55A, E55, E55A, 56TC, A56TC, 58, 95, B95, B95A, D95A, and E95 Airplanes	Landing Gear Uplock Rollers	10/25/1972

Airframe ADs: Model S35 Bonanza

from www.faa.gov

72-11-02	BEECH Models F33, G33, F33A, V35B, V35B-TC, A36, 95-B55, 95-B55A, 95-B55B, E55, E55A, 58, 58A, 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, E33C, F33C, K35, M35, N35, P35, S35, V35, V35-TC, V35A, V35A-TC, 36, 35, 35R, A35, B35, C35, D35, E35, F35, G35, H35, J35, 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B, 95-C55, 95-C55A, D55, D55A, 95, B95, B95A, D95A and E95 Airplanes	Engine Fuel Interruption	05/20/1972
70-03-05	BEECH Models H35, J35, K35, M35, N35, P35, S35, S35TC, V35, V35-TC, V35A, V35A-TC, 35-33, 35-A33, 35-B33, 35-C33, E33, 35-C33A, E33A, Model F33C, E33C, 36 Airplanes	Turning Type Takeoffs	06/30/1972
64-27-01	Beech Model P35 and S35 Airplanes	Control Wheel Column Aft Stop	12/07/1964